

ROOF			
Member Name	Results	Current Solution	Comments
BM R1	Passed	1 piece(s) 6 x 10 Douglas Fir-Larch No. 2	
BM R2	Passed	1 piece(s) 4 x 8 Douglas Fir-Larch No. 2	
BM R3	Passed	1 piece(s) 4 x 8 Douglas Fir-Larch No. 2	
BM R4	Passed	1 piece(s) 6 x 10 Douglas Fir-Larch No. 2	
BM R5	Passed	1 piece(s) 4 x 10 Douglas Fir-Larch No. 2	
BM R6	Passed	1 piece(s) 4 x 8 Douglas Fir-Larch No. 2	
BM R7	Passed	1 piece(s) 4 x 8 Douglas Fir-Larch No. 2	
BM R8	Passed	1 piece(s) 4 x 8 Douglas Fir-Larch No. 2	
BM R9	Passed	1 piece(s) 4 x 12 Douglas Fir-Larch No. 2	
BM GL1A	Passed	1 piece(s) 3 1/2" x 11 7/8" 24F-V4 DF Glulam	
BM GL2A	Passed	1 piece(s) 3 1/2" x 11 7/8" 24F-V4 DF Glulam	
REF RAFTER 5	Passed	1 piece(s) 2 x 12 Douglas Fir-Larch No. 2 @ 24" OC	
SECOND FLOOR			
Member Name	Results	Current Solution	Comments
BM S1	Passed	1 piece(s) 1 3/4" x 11 7/8" 1.55E TimberStrand® LSL	
BM S2	Passed	1 piece(s) 1 3/4" x 11 7/8" 1.55E TimberStrand® LSL	
BM S3	Passed	1 piece(s) 4 x 8 Douglas Fir-Larch No. 2	
BM S4	Passed	1 piece(s) 3 1/2" x 11 7/8" 1.55E TimberStrand® LSL	
BM S5	Passed	1 piece(s) 3 1/2" x 11 7/8" 1.55E TimberStrand® LSL	
BM S6	Passed	1 piece(s) 4 x 8 Douglas Fir-Larch No. 2	
BM S7	Passed	1 piece(s) 3 1/2" x 11 7/8" 1.55E TimberStrand® LSL	
BM S8	Passed	1 piece(s) 4 x 10 Douglas Fir-Larch No. 2	
BM S9	Passed	1 piece(s) 1 3/4" x 11 7/8" 1.55E TimberStrand® LSL	
BM S10	Passed	1 piece(s) 1 3/4" x 11 7/8" 1.55E TimberStrand® LSL	
BM S11	Passed	1 piece(s) 4 x 8 Douglas Fir-Larch No. 2	
BM S12	Passed	1 piece(s) 4 x 8 Douglas Fir-Larch No. 2	
BM S13	Passed	1 piece(s) 4 x 10 Douglas Fir-Larch No. 2	
BM S14	Passed	1 piece(s) 4 x 10 Douglas Fir-Larch No. 2	
BM S15	Not Designed	1 piece(s) 1 3/4" x 11 7/8" 1.55E TimberStrand® LSL	
BM S16	Passed	1 piece(s) 4 x 8 Douglas Fir-Larch No. 2	
BM S17	Passed	1 piece(s) 4 x 8 Douglas Fir-Larch No. 2	
BM S18	Not Designed	1 piece(s) 5 1/2" x 18" 24F-V4 DF Glulam	
BM S19	Passed	1 piece(s) 5 1/2" x 12" 24F-V4 DF Glulam	
BM GL1B	Passed	1 piece(s) 5 1/2" x 11 7/8" 24F-V4 DF Glulam	
BM GL2B	Passed	1 piece(s) 3 1/2" x 11 7/8" 24F-V4 DF Glulam	
BM GL2C	Passed	1 piece(s) 3 1/2" x 11 7/8" 1.55E TimberStrand® LSL	
BM GL3	Passed	1 piece(s) 5 1/2" x 18" 24F-V4 DF Glulam	
BM GL4B	Passed	1 piece(s) 5 1/2" x 13 1/2" 24F-V4 DF Glulam	
BM GL4C	Passed	1 piece(s) 5 1/2" x 13 1/2" 24F-V4 DF Glulam	
BM LVL1	Passed	1 piece(s) 1 3/4" x 11 7/8" 2.0E Microllam® LVL	
BM LVL2A	Passed	1 piece(s) 1 3/4" x 11 7/8" 2.0E Microllam® LVL	
BM LVL2B	Passed	1 piece(s) 1 3/4" x 11 7/8" 2.0E Microllam® LVL	
BM LVL2C	Passed	1 piece(s) 1 3/4" x 11 7/8" 2.0E Microllam® LVL	
BM LVL2D	Passed	1 piece(s) 1 3/4" x 11 7/8" 2.0E Microllam® LVL	
BM LVL2E	Passed	1 piece(s) 1 3/4" x 11 7/8" 2.0E Microllam® LVL	
BM GL2D	Passed	1 piece(s) 3 1/2" x 11 7/8" 24F-V4 DF Glulam	
Deck			
Member Name	Results	Current Solution	Comments
BM D1	Passed	1 piece(s) 4 x 10 Hem-Fir No. 2	
BM D2	Passed	1 piece(s) 4 x 10 Hem-Fir No. 2	

ForteWEB Software Operator	Job Notes
Luke Bruckelmyer Ek Engineering (360) 687-7668 LukeB@EKEngineering.net	Pegors Beach House 32207 G St Ocean Park, WA For: Doug & Denise Pegors