| Member Name         | Results | Current Solution                               | Comments |
|---------------------|---------|--|----------|
| Porch Beams         |         |  |          |
| Line 2 (worst case) | Passed  | 1 piece(s) 6x10 Douglas Fir-Larch No.1         |          |
| Line A              | Passed  | 1 piece(s) 6x8 Douglas Fir-Larch No.1          |          |
| Line 3              |         |  |          |
| 6ft Header          | Passed  | 1 piece(s) 6x8 Douglas Fir-Larch No.1          |          |
| 4ft Header          | Passed  | 1 piece(s) 6x6 Douglas Fir-Larch No.1          |          |
| Line 1              |         |  |          |
| 5ft Header          | Passed  | 1 piece 6x6 Douglas Fir-Larch No.2             |          |
| 3ft Header          | Passed  | 1 piece 4x6 Douglas Fir-Larch No.2 (Plank)     |          |
| Line B              |         |  |          |
| 6ft Header          | Passed  | 1 piece 6x6 Douglas Fir-Larch No.2             |          |
| 5ft Header          | Passed  | 1 piece 4x6 Douglas Fir-Larch No.2 (Plank)     |          |
| Line E              |         |  |          |
| Garage Door Header  | Passed  | 1 piece(s) 5 1/4" x 11 7/8" 2.2E Parallam® PSL |          |