

Porch Beams			
Member Name	Results	Current Solution	Comments
Line 2 (worst case)	Passed	1 piece(s) 6 x 10 Douglas Fir-Larch No. 1	
Line A	Passed	1 piece(s) 6 x 8 Douglas Fir-Larch No. 1	
Line 3			
Member Name	Results	Current Solution	Comments
6ft Header	Passed	1 piece(s) 6 x 8 Douglas Fir-Larch No. 1	
4ft Header	Passed	1 piece(s) 6 x 6 Douglas Fir-Larch No. 1	
Line 1			
Member Name	Results	Current Solution	Comments
5 ft Header	Passed	1 piece(s) 6 x 6 Douglas Fir-Larch No. 2	
3 ft Header	Passed	1 piece(s) 4 x 6 Douglas Fir-Larch No. 2 (Plank)	
Line B			
Member Name	Results	Current Solution	Comments
6ft Header	Passed	1 piece(s) 6 x 6 Douglas Fir-Larch No. 2	
5ft Header	Passed	1 piece(s) 4 x 6 Douglas Fir-Larch No. 2 (Plank)	
Line E			
Member Name	Results	Current Solution	Comments
Garage Door Header	Passed	1 piece(s) 5 1/4" x 11 7/8" 2.2E Parallam® PSL	

ForteWEB Software Operator	Job Notes
Calvin Fernandes Fernandes Engineering (805) 610-7019 calvinf@sbcglobal.net	

