

is there a way to trigger a report 'note' to user to verify need for hanger corrosion protection due to treated wood?

Beam

Ledger on masonry

Plate on concrete

Plate on steel

Stud wall

TJI®

Masonry wall with embedded hanger

Steel beam with welded connector

Beam

Douglas Fir-Larch

None

Options

Beam

Douglas Fir-Larch

None

Options

say: Treated plate on masonry/concrete

New: Ledger on stud wall

New: Strandguard LSL 2x4/2x6/?? plate on Masonry/Concrete

Span 2

port 2

50"

Hanger